

No : 05 / 2021
Date : 12 Aug 2021
Rescission Date : NA



AIRPORT EMERGENCY SERVICE

FIRE PREVENTION CIRCULAR

To All Airport Partners

COMPLIANCE WITH SCDF FIRE CODE REQUIREMENTS ON THE PROVISION OF 50KG FIRE EXTINGUISHER(S) IN TROLLEY WITHIN HOARDED AREA(S)

Under the Fire Code, clause 9.9.4.C.(1c), stipulates that “Within the hoarded area(s), 50kg fire extinguisher(s) in trolley shall be provided near the hoarding exit access door. Each fire extinguisher shall not cover more than 20m.”. Please do take note that the use of multiple smaller fire extinguishers to achieve the 50kg requirement is not permitted.

2 AES would like to send a strong reminder to airport partners and renovation contractors to ensure strict compliance with the Fire Code.

3 For further clarifications, you may contact the Fire Prevention Section (FPS) of the Airport Emergency Service at 6541 2535 or e-mail to: fire.safety@changiairport.com.

A handwritten signature in black ink, appearing to be "Addison Low".

ADDISON LOW
Head, Fire Prevention Section
Airport Emergency Service